|                                       | ·  |                                       |   |  |                              |  |   |  |  |
|---------------------------------------|--|---------------------------------------|---|--|------------------------------|--|---|--|--|
|                                       |  |                                       |   | _  |                              |  |   |  |  |
| me <u>BX-6714</u>                     | Mission Nr /4 Date /5/8066   |                                       |   | 7 H-hour 0225 Z 1125L  |                              |  |   |  |  |
| ilot                                  | A Fostr D. B. B Fostr D.M. C Fostr J. Y.  A Obsvr B Obsvr C Obsvr  |                                       |   |  |                              |  |   |  |  |
| М                                     |  |                                       | Duty Hours Duty Hours Duty Hours  |  |                              |  |   |  |  |
|                                       | ON   | DOI                                   | RESP<br>IND <b>V</b>  | TIME<br>DUE(Z)   | TIME<br>DUE(L)               | TIME<br>DONE(L)  | DONE BY (Initials                                     |  |  |
| Start this che                        | ck list  | B-3                                   |   | 0235   | 1125                         | 1100   | DM  |  |  |
| Arrange work s                        | chedule  | B-4                                   |   | 0225   | 1125                         |  |   |  |  |
| Attend Command                        | Attend Commander's Briefing  |                                       |   | 0400   | 1300                         |  |   |  |  |
| Rcv (Pre                              | lim Ops Data)  | B-1                                   |   | 0325   | 1225                         |  |   |  |  |
| Coordinate TTF                        | C support  | B-2                                   |   | 0355   | 1255                         |  |   |  |  |
| Give prelim de                        | ia to TTF  | B-2                                   |   | 0400   | 1300                         |  |   |  |  |
| Rcv (Tm                               | nl fcsts)  | B-5                                   |   | 0525   | 1425                         | 1315   | Deb   |  |  |
| Start Met Watc                        | h on wall map  | B-21                                  |   | 0525   | 1425                         |  | Other   |  |  |
| Rev (Mis                              | sion wx data)  | B-6                                   | :   | 0525   | 1425                         | 1345   | SI  |  |  |
| Pick up APT pi                        | ctures   | B-10                                  | ,   | 0530   | 1430                         |  |   |  |  |
| Rev (Co                               | mposite rte data)  | B-6                                   |   | Vrbl   | Vrbĺ                         |  |   |  |  |
|                                       |  | B-6                                   |   |  |                              |  |   |  |  |
| 1                                     |  | B <b>-</b> 5                          |   |  |                              |  |   |  |  |
|                                       |  |                                       | ļ   |  |                              |  |   |  |  |
|                                       | ,  |                                       |   |  |                              |  |   |  |  |
|                                       | •  |                                       |   |  |                              |  |   |  |  |
|                                       |  |                                       | 1   |  |                              |  |   |  |  |
| rcv (Fin                              | ai Ups data)   | B-0                                   |   | 1220   | 2250                         |  |   |  |  |
| · · · · · · · · · · · · · · · · · · · |  | <del> </del>                          |   |  |                              |  |   |  |  |
| pproved For Rele                      | ase 2001/04/20 : CI  | A-RD                                  | P69B00  | 041R002  | 3000500                      | 01-8   |   |  |  |
|                                       | Start this che Arrange work s Attend Commend Rev (Pre Coordinate TTF Give prelim de Rev (Tm Start Met Watc Rev (Mis Pick up APT pi Rev (Co Rev Amen Rev (Tm Brief pilot an Rev letdown pl Rev (Tan Letdown plates Rev (Fin | (As of 14 July ame BX-67/4 Mission Nr | (As of 14 Jul 67;  ame BX-67/4 Mission Nr /4  Lot B Fostr D.B. Plot C Fostr J.Y.  A Obsvr B Obsvr C Obsvr  B ACTION DOI  Start this check list B-3  Arrange work schedule B-4  Attend Commander's Briefing B-1  Rev (Prelim Ops Data) B-1  Coordinate TTFC support B-2  Give prelim tata to TTFC B-2  Rev (Mission wx data) B-5  Start Met Watch on wall map B-21  Rev (Mission wx data) B-6  Pick up APT pictures B-10  Rev (Composite rte data) B-6  Rev (Tmnl fosts) B-5  Brief pilot and ops staff B-7  Rev letdown plates from DCOM B-14  Rev (Tanker msn wx fost) B-9  Letdown plates to DCO B-14  Rev (Final Ops data) B-8 | (As of 14 Jul 67; with to the problem of the proble | A Fostr   D. B.   Duty Hours | (As of 14 Jul 67; with tankers)  Ame BX 6714 Mission Nr /Y Date SAUGE A H-hot  A Fostr D. B. Duty Hours Pilot B Fostr D. M. Duty Hours Pilot B Obsvr Duty Hours Pord A Obsvr Duty Hours Plant | (As of 14 Jul 67; with tankers)    As   B   C   C   C |  |  |

Approved For Release 2001/04/20 : CIA-RDP69B00041R002300050001-8

|          | BLACK &       | SPIELD CHECK LIST (as of Be Jul 67                                  |               |                                | Page 2          |                 |                |                      |
|----------|---------------|---|---------------|--------------------------------|-----------------|-----------------|----------------|----------------------|
|          | H-Minus       | ACTION  | DOI           | RESP<br>INDV                   | TIME<br>DUE(Z)  | TIME<br>DUE(L)  | TIME<br>DONE(L | DONE BY<br>Initials) |
| 25X1A    | -10:00        | Send (Termin wx fcsts)  | B <b>-5</b>   |                                | 1625            | 0125            |                |                      |
|          | -9:00         | Rcv (GO-NO GO wx fcsts)   | B <b>-1</b> 1 |                                | 1725            | 0225            |                |                      |
| 25X1A    | -9:00         | Give input to Msn Coord   | B-23          |                                | 1725            | 0225            |                | <br>                 |
|          | -8:00         | Send (thru L-hr, if redd)   | B <b>-1</b> 6 |                                | 1825            | 0325            |                |                      |
|          |               | Annotate tanker DD Forms 175  | B <b>-2</b> 4 |                                |                 |                 |                |                      |
|          |               | Brief tankers   | B <b>-24</b>  |                                |                 |                 |                |                      |
| 25X1A    | -4:00         | Send (Terminal wx fcsts)  | 3 <b>-</b> 5  | -                              | 2225            | 0725            |                |                      |
| 25X IA   | -4:00         | Send (Met Watch obs)  | B <b>-1</b> 8 |                                | 2225            | 0725            |                |                      |
|          | <u> </u>      | Brief tankers   | B <b>-2</b> 4 |                                |                 | ,               |                |                      |
|          | · -3:30       | Brief pilots and ops staff  | B <b>-2</b> 0 |                                | 2255            | 0755            |                |                      |
| <u> </u> |               | Brief tenkers   | B <b>-2</b> 4 |                                |                 |                 | `              | 4.                   |
| 25X1A    | -3:00         | Rcv Amend (GO/NO GO fcsts)  | B <b>-11</b>  |                                | 2325            | 0825            |                |                      |
| . =      | -3:00         | Rcv idown Plates from DCO   | B-14          |                                | 2325            | 0825            |                |                      |
|          | -3:00         | Enter fosts on Letdown Plates                                       | B <b>-1</b> 4 |                                | 2325            | 0825            |                |                      |
|          | -2:30         | Msn Obsvr to CP; posts data   | B <b>-1</b> 3 |                                | 2355            | 0855            |                |                      |
| 25X1A    | -2:00         | Rcv (Wx Scout reports)  | B-22          | :                              | 0025            | 0925            |                | -                    |
|          |               | Pick up APT pictures  | B <b>-1</b> 0 |                                | 0000<br>or ASAP | 0900<br>or ASAP |                |                      |
| ( ) 8    | -1:40         | Msn Fcstr to CP; Obsvr to wx stn                                    | B <b>-13</b>  |                                | 0045            | 0945            |                |                      |
|          | -1:35         | Letdown plate fcsts to pilots<br>(Notify Mission Coordinator)       | B <b>-1</b> 4 |                                | 0050            | 0950            |                | Ť                    |
|          | -1:30         | Notify DCOL (If need to rebrief pilots)                             | 3-20          |                                | 0055            | 0955            |                |                      |
|          | -1:10         | Rebrief pilots if necessary   | 3-20          |                                | 0115            | 1015            |                |                      |
| :        | L-Plus        | Landing time: Z L   |               |                                |                 |                 | <u> </u>       |                      |
|          | +0:15         | Return Met Watch to wx station                                      | 3-13          |                                |                 |                 |                |                      |
|          | +0:15         | Start debriefing form   | 3-15          |                                |                 |                 |                |                      |
| 25X1A    | <b>4</b> 0:45 |   | 3-15          |                                |                 |                 |                |                      |
| \        | ASAP          | Give input to DCOM Coord after debriefing                           | -15           |                                | ASAP            | ASAP            | 1              |                      |
|          | +24:00        | Turn in Man Wx File to Intell Boroved For Release 2001/04/20 : CIA- | <b>517</b>    | <b>6 D 0 0 0 0 0 0 0 0 0 0</b> | 44B0000         | 005000          |                |                      |
|          | Ар            | proved For Release 2001/04/20 : CIAFI                               | KUNO          | 90000                          | 4 IKUUZ3U       |                 |                |                      |
|          |               | ·   |               |                                | I               |                 |                |                      |